

# Present status of JSNS mercury target

Katsuhiro Haga, Hiroyuki Kogawa, Takashi Wakui,  
**Takahsi Naoe**, Eiichi Wakai, Hiroshi Takada


J-PARC Center, JAEA

# Outline


---

- **Status of JSNS target for the last two years**
- **Outline of the target troubles in 5th and 7th targets**
- **Strategy of design and fabrication improvements**
- **Improved design and inspection of 8th target**
- **Summary**



# JSNS 1MW spallation neutron source





# JSNS bubbling system



*Swirl type bubble generator*




*#3 target vessel with bubble generator*



*JSNS mercury circulation system (Closed helium gas loop)*


- Swirl type microbubble generator was installed from 3rd target vessel with gas circulation system to mitigate proton beam-induced pressure waves
- Peak bubble radius is 30 μm, void fraction (He/Hg flow ratio) is  $10^{-2}$  at bubble generator

# Operation status for the last two years




- 5th target was failed a month after ramping up power to 500 kW
- 7th target (repaired) was failed two weeks after restarting operation at 500 kW
- **Both targets operation were stopped due to leak of cooling water**
- 2nd target should be used till June 2017 (beam power is limited less than 200 kW), because we have no spare target of different structure from the failed targets
- Fabrication of 8th target is now going on and will delivery at next June

# High power beam experiment up to 1MW<sub>equiv.</sub>




*LDV time responses for 3rd and 7th target*



*LDV peak amplitude obtained from 7th target*

- Target system has the LDV diagnostic system (LDV, Mirror)
- Peak amplitude of 1 MW<sub>equiv.</sub> study (OCT. 2015) showed similar amplitude of 300 kW W/O bubble ➡ **Bubbles extremely mitigates pressure waves**
- Peak amplitude of velocity for bubbles case seems to be 1/4 of W/O bubbles cases


# High-power beam experiment at 25 Hz



*Beam experiment history of 7th target (25 Hz)*

- 25 Hz beam experiment performed under injecting gas microbubbles
- Gas flow ratio is constant but mitigation effect shows large variation  
> bubble distribution at beam window is fluctuating
- In high-power operation, accelerator seems unstable (in my opinion)

# Troubles in 2015 — 5th and 7th targets —



- 5th and 7th targets were failed due to water leak at water shroud
- Leak sensor at the drain tank of helium vessel was detected leak for 5th target  
Water leaked to outside of target vessel
- Leak sensor inside target vessel was detected leak for 7th target  
Water leaked to inside of target vessel


**Radioactive gas was not released from stack (Leak occurred in enclosed vessel)**

# Structure of mercury target vessel


5th target vessel



Current design (~5th target)



Triple walled structure






Vertical cross section of the target viewed from the target side

Vertical cross section of the target viewed from the target side

- Target vessel has triple walled structure (Inner/Outer water shroud, Mercury vessel)
- Outer and inner water shroud (diffusion bonded) was bolted to mercury vessel
- Bolt head and outer/inner shroud interface was welded by GTAW

# Visual inspection for detecting leak location




- Observation of target surface by video camera
- Pressurizing water shroud with helium gas (0.16 MPaG)
- A water drop found on the bottom side surface (**Determined leak location**)
- Crack caused by welding defect was found on leak location

# Failure mechanism of 5th target

## Fabrication process


Diffusion bonding

**Ultrasonic inspection was passed**



Bolt water shroud to on mercury vessel



Plug bolt head with weld metal



**Diffusion bonded interface was detached by thermal deformation**


Seal welding w/o groove to ensure airtightness in water shroud

**Leak tightness test was passed**



## Beam operation


**Seal welding of thin penetration depth (<1.5 mm) was failed by repeated thermal stress**




- Crack propagated through the seal welded part between inner and outer shroud
- Total number of thermal cycles due to beam trip for 5th target is ca. 2500
- Structural design, that allowed the seal welding without groove, was attributed to the water leak

# Reinforced structure of 7th target




## Original design



## Remove seal welding and diffusion bonded layer



## Repair welding (leave a weld bead) 3 path



*Cross section of mock-up specimen*




*Repaired 7th target vessel*

- Spare target (7th target) which is the same design with 5th target was repaired to eliminate seal welding without groove
- 167 portion of around bolts were repaired and beam operation with repaired 7th target was started from Oct. 2015
- **7th target was failed two weeks after restarting operation at 500 kW**

# Sound measurement for detecting leak location




Triple point of welding





Repaired point of around bolt

***No-visible change was found from outside inspection***



Auscultation rod




Pressurize water shroud (0.5 MPa)

- Prepared microphones to detect the sound of gas ejecting from inner water shroud
- However, passage of gas between helium layer and water layer was closed when we tried to measure sound

***We retried sound measurement in this October, but still unclear the leak location***

# A possible reason for leak of 7th target




**Details of failure analysis for 7th target will be shown in Wakui's talk on Wednesday**

- Monolithic structure around mirror for LDV system seems to be leak location
- Welding defect (unconnected region) acts as notch for propagating fatigue crack by pressure waves and thermal stress
- But we did not find any change in LDV signals just before failure

# Strategy of design & fabrication improvements

## Failed at 500kW operation




*Many welds incl. diffusion bonding with constraints between vessels*

**1st~7th (previous)**

## Improved structure

Monolithic structure of water shroud & Hg vessel




Monolithic structure of water shroud

*Much fewer welds with constraints*

**8th(next)**

## Future plan for high power operation

Constraint-free



Helium layer

*Few welds with no constraints*

**10th or later**


For 8th target

- Reducing welding parts as few as possible (reduced to 70%)
- Adopting fabrication processes which makes inspections of welding lines easier


Added for 10th or later targets

- Minimizing the constraints between water shroud and mercury vessel to reduce thermal stress

# Heat density and thermal stress



Heat density distribution at 1MW



Stress range in rear part


Thermal stress distribution for inner water shroud at 1 MW

- Heat density in rear part is less than 1/4 of fore part
- Thermal stress is less than half of allowable stress

**Bolt structure in rear part is enough to withstand thermal stress at 1 MW**

# Lesson and improvement from failures


## Improvement for 8th target





**Wire EDM was applied to reduce welding line and to eliminate diffusion bonding**

- Lack of penetration depth for seal welding led leakage of water (5th target)  
Fatigue crack was propagated thermal cycles by beam trip from weld defect
- Monolithic structure of LDV mirror base seemed to be induce un-welded region which acts as notch, and fatigue crack propagated by pressure waves

# Improvement of inspection



Inspection of mock-up specimen by phased array & Full Matrix Capture (FMC) / Total Focusing Method (TFM)




## Radiographic Testing (RT)

## Ultrasonic Testing (UT)

*Details of nondestructive inspection for target vessel will be shown in Wakui's poster*

- Based on the experiences of target failure, we revised the inspection procedure  
*RT : Front part of mercury vessel only (~7th) → All part including water shroud (8th~)*
- UT inspection will be added :  
*Nondestructive inspection method: phased array & FMC/TFM method (GEKKO, Insight)*

# Power upgrade scheme towards 1 MW



- Ramp up proton beam power step by step with ~100 kW
- We should keep 200 kW operation due to delay of delivery of 8th target until June, 2017
- Storage building is under construction, and operation will start from 2018

# Summary

---




- 1 MW<sub>equiv.</sub> beam experiment was achieved in 2015, and confirmed excellent effect of injecting gas microbubbles on pressure wave mitigation by LDV measurement
- Current beam power of JSNS is 200 kW, 2nd target (w/o bubble injection system) is under operation
- The causes of water leak for 5th and 7th targets are welding defect and structural design
- Design, fabrication, and inspection were improved based on the lessons learned from the target failures (reduce of welding lines to 70% by adopting monolithic structure using wire-EDM)
- The constraint-free type structure will be adopted for 10th or later targets aiming for the 1MW stable beam operation



---


# Backup slides

# Maintenance work in 2016 Related to target system



- Pressure sensors, which were damaged by neutron irradiation and showed strange value, were replaced new type sensors (Rosemount sensor)
- Grease the bearing and motor for mercury pump by remote handling  
 Design life of motor for mercury pump is 10 years (8y /10y now)
- Erosion of mercury channel for mercury pump in which thickness is 5 mm was measured using ultrasonic thickness gage by remote handling  
 No-obvious erosions were detected after about 8 years operation

# Water leak from welding defect



- Crack propagated through the seal welded part between inner and outer shroud
- Seal welding without groove was performed by GTAW to satisfy only seal performance
- Penetration depth is less than 1.5 mm (Structural strength is not expected)

# Failure mechanism of 5th target

## Fabrication process

Diffusion bonding

Ultrasonic inspection was passed

Bolt water shroud to on mercury vessel

Plug bolt head with weld metal



Diffusion bonded interface was detached by thermal deformation

Seal welding to ensure airtightness in water shroud

Leak tightness test was passed


Beam operation

Seal welding of thin penetration depth was failed by repeated thermal stress




- Total number of thermal cycles due to beam trip for 5th target is ca. 2500
- Structural design, that allowed the seal welding without groove, was attributed to the water leak

# Water leak of 7th target




## How we judged the water leakage

- No-mercury related radio active gas was detected by gas monitoring system
- Electric resistance of sensor showed 5~6 k $\Omega$  (same as water)
- Pressure of helium layer correlated closely with pressure change in water layer



- 7th target was failed by water leak two weeks after starting 500 kW operation
- Two leak sensors detected leak in operation Nov 20th, 2015
- **Leak location was inner water shroud, but not yet found pinpoint location**

# Inspection of specimen cut out from 5th target



- Beam window of failed target vessel was cut to observe cavitation damage inside mercury vessel
- Cavitation damage on narrow channel was measured by replica method
- Innermost surface of beam window could not cut due to broken of cutter

*Details of damage inspection will be shown on Thursday*

# Operational histories of JSNS targets

<i>Damage mitigation technologies</i>	2008	2009	2010	2011	2012	2013	2014	2015	2016
<b>Surface hardening</b>	1st target Max. 220 kW 471 MWh						2nd target Max. 220 kW		
<b>Surface hardening + Injecting microbubbles</b>				3rd target Max. 310 kW 2050 MWh					
<b>Surface hardening + Injecting microbubbles + Double wall</b>				5th target Max. 513 kW 670 MWh			7th target Max. 505 kW 170 MWh		

*Note: The table includes visual elements such as colored bars (green, blue, orange, red) and text annotations like 'In operation' and 'Water shroud failed' indicating operational status and issues.*

- 1st operation was stopped due to the earthquake
- 4th & 6th targets (spare) has the same structure with 5th target
- 5th & 7th targets operation were stopped by trouble of water shroud
- Fabrication 8th target is now going on and will delivery at next June